


39 Mustang Avenue Box Hill NSW

6  3  2 

Regarding the property, the following outstanding jobs still require follow-up:

Driveway paint

The sealer attended today but advised they had not received any instruction from the office regarding painting the driveway. After I called your team, I was told the sealer would be informed; however, the driveway has still not been painted.

Could you please re-arrange a new time for this work?

Replace digital locker & seal bathroom basin

We were previously advised that Ali would attend yesterday, but he did not arrive. Please kindly provide an updated schedule.

Seal hairline cracks

This has currently been booked for 1 May.

Price : House with Granny Flat

View : <https://www.spgr.com.au/sale/nsw/western-sydney/box-hill/residential/house/8683818>



Successful Properties
9688 2097

Please assist in confirming the updated timelines for items